

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

KAWAILII BRIDGE  
(Kawaili Stream Bridge)  
Spanning Kawailii Gulch at Hawaii Belt Road  
Paauilo  
Hawaii County  
Hawaii

HAER No. HI-94

David Franzen, Photographer

July 2010

- |         |   |
|---------|---|
| HI-94-1 | ELEVATION OF THE SOUTH PARAPET. VIEW FACING NORTHEAST.  |
| HI-94-2 | WEST APPROACH TO THE KAWAILII BRIDGE. VIEW FACING SOUTHEAST   |
| HI-94-3 | EAST APPROACH TO THE BRIDGE. THE STRUCTURE IN THE LEFT BACKGROUND IS THE TEMPORARY BYPASS BRIDGE. VIEW FACING NORTHWEST.  |
| HI-94-4 | STREAMBED AND UNDERSIDE OF KAWAILII BRIDGE SHOWING THE REMNANTS OF EARLIER ABUTMENT ON EAST ABUTMENT AT LEFT. NOTE THE BATTERED CONCRETE SURFACE OF THE UPPER PORTION OF THIS EARLIER ABUTMENT. VIEW FACING WEST.                       |
| HI-94-5 | STREAMBED, UNDERSIDE, AND EAST ABUTMENT OF THE BRIDGE SHOWING THE QUARRY FACED MASONRY OF THE 1938 CONSTRUCTION. NOTE THE BATTERED CONCRETE SURFACE OF THE EARLIER ABUTMENT IN BACKGROUND. VIEW FACING EAST.                            |
| HI-94-6 | DETAIL OF UN-COURSED RUBBLE WORK OF EARLIER ABUTMENT AT WEST ABUTMENT. VIEW FACING WEST.  |
| HI-94-7 | UNDERSIDE OF THE BRIDGE DECK SHOWING T-BEAM CONSTRUCTION. NOTE THE HORIZONTAL CONCRETE BEARING ATOP THE QUARRY FACED MASONRY ABUTMENT. THE CENTER, PAIRED BEAMS ARE ON THE RIGHT. VIEW FACING NORTHWEST.                                |
| HI-94-8 | OBLIQUE VIEW OF THE MAUKA PARAPET. NOTE THE CURVE OF THE SIDE OF THE STANCHIONS NOT FACING THE ROADWAY. THE TEMPORARY BYPASS BRIDGE DIVERTING TRAFFIC AROUND THE KAWAILII BRIDGE IS SEEN IN THE LEFT BACKGROUND. VIEW FACING NORTHWEST. |

- HI-94-9      DETAIL OF THE EAST STANCHION OF THE MAKAI PARAPET SHOWING 1938 YEAR DATE INSCRIPTION. NOTE THE STEPPED TREATMENT AT THE CORNERS OF THE STANCHION. VIEW FACING NORTHEAST.
- HI-94-10     DETAIL OF THE EAST STANCHION OF THE MAUKA PARAPET SHOWING THE INSCRIPTION "KAWAILII." VIEW FACING SOUTHWEST
- HI-94-11     DETAIL OF A TYPICAL SECTION OF PARAPET SHOWING THE CROSS SHAPED VOIDS IN RECESSED PANELS BETWEEN THE BALUSTERS. NOTE THE RECESSED CORNERS OF THE TOP RAIL. VIEW FACING NORTHWEST.

PHOTO KEY

